## CBE 770 — Advanced Process Dynamics and Control. Model Predictive Control and Moving Horizon Estimation Spring 2009

Homework 1 Exercises 1.1, 1.4, 1.5, 1.6, 1.10	Due: Tuesday, January 27
Homework 2 Exercises C.1, 1.15, 1.16, 1.17, 1.18, 1.19	Due: Thursday, February 5
Homework 3 1.45, 1.50, 1.51, 1.52, 1.53	Due: Thursday, February 12
Homework 4 1.13, A.30, A.32, 1.20	Due: Thursday, February 19
Homework 5 1.28, 1.31, 1.56, 1.60	Due: Thursday, February 26
Homework 6 B.2, B.3, B.4, B.5	Due: Thursday, March 5
Midterm	Monday, March 9
Homework 7 2.4, 2.5, 2.6	Due: Tuesday, April 7
Homework 8 2.7, 2.8	Due: Tuesday, April 14
Homework 9 4.3, 4.8, 4.10, 4.16	Due: Tuesday, April 21
Homework 10 6.1, 6.6, 6.10	Due: Tuesday, April 28
Homework 11 6.15, 6.18, 6.19	Due: Tuesday, May 5
Final	Wednesday, May 13